## Oil Field Environmental Incident Summary

Responsible Party: Zenergy, Inc.
Well Operator: ZENERGY, INC
Well Name: SANDBERG 1-21H

Field Name: EAST FORK Well File #: 14659

Date Incident: 3/30/2013 Time Incident: 12:00 Facility ID Number:

County: WILLIAMS Twp: 156 Rng: 100 Sec: 21 Qtr: SW SE

Location Description:

Submitted By: Chad Hillesland Received By:

Contact Person: Chad Hillesland

6100 S YALE AVE STE 1700

TULSA, OK 74136

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Leak

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

	Spilled	Units	Recovered	Units	
Oil	0	barrels	0	barrels	
Brine	10	barrels	10	barrels	
Other	0	barrels	0	barrels	

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

None.

Areal Extent:

Followup Units

## Potential Environmental Impacts:

None.

## Action Taken or Planned:

Shut down well, vac truck bottomed out SW tank and cleaned up SW spilled in dike.

Wastes Disposal Location: SWD

Agencies Involved:

## **Updates**

Date: 5/6/2013 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Release remained on location, within the diking, according to the report.